





Produktänderungsinformation

QMPA\_Produktänderung\_2025-01\_RM45\_RM46\_RM29\_RM66\_RM84.odt  
Blatt 1 von 2

## Produktänderungsinformation



**Ausgabedatum:** 2025-01  
**Betroffene Artikel:** RM45, RM46, RM29, RM66, RM84  
**Beschreibung der Änderung:** Gehäuse

Parameter	alt	neu
Gehäusematerial	Noryl/Lexan, UL 94 V-0	PC/ABS, UL 94 V-0
Abmessungen	 	 
V.24 Stecker	RJ-45	15 pol. SUB-D Buchse
Isolation V.24 zu Analogausgang	keine galv. Isolation, GND ist nicht auf Potential von Analog OUT-	4-Wege-Trennung (Versorgung, Messkreis, Analog OUT, V.24)

**Änderung Datenblatt:** Januar 2025  
**Lieferung ab:** 2025-05  
**Identifikation:** Durchgängig rote Displayfront

## Product Change Notification

**Issue date:** 2025-01  
**Affected products:** RM45, RM46, RM29, RM66, RM84  
**Object of change:** change of case

Parameter	old	new
Case material	Noryl/Lexan, UL 94 V-0	PC/ABS, UL 94 V-0
Dimensions		
V.24 connector	RJ-45	15 pin SUB-D female
Isolation V.24 to analog out	no galvanic isolation, GND is not of same level as analog OUT-	4-way-isolation (supply, measure input, analog OUT, V.24)

**Change of data sheet:** January 2025  
**Effective from:** 2025-05  
**Identification:** All-red display front